

San José del Palmar - Chocó, Colombia

ID del sismo: SGC2026pqqmro

Magnitud:	7.4	Hora local:	2026-08-10 07:34:27	Latitud:	4.99°
Profundidad:	103 km	Hora UTC:	2026-08-10 12:34:27	Longitud:	-76.29°

Anserma, Caldas, Colombia	CM	CANSE	5.26	-75.81	10	1932	61	120	223.211249	200.958038	37.150375
Pereira, Risaralda, Colombia	CM	CBOCA	4.78	-75.65	10	1529	75	128	17.251509	17.908504	9.050726
Riosucio, Caldas, Colombia	CM	RIO2C	5.42	-75.71	10	1958	80	131	21.781621	38.196462	20.338773
Filandia, Quindio, Colombia	CM	FLND	4.69	-75.62	10	2035	82	132	422.651827	268.305636	105.494656
Armenia, Quindio, Colombia	CM	ARMEC	4.56	-75.66	10	1554	85	134	198.706	221.842718	80.787229
Circasia, Quindio, Colombia	CM	CIRS	4.64	-75.61	10	1980	85	134	274.918132	387.878959	90.065842
Trujillo, Valle del Cauca, Colombia	CM	CTRUJ	4.22	-76.32	10	1388	86	134	93.82152	129.795181	81.687681
Manizales, Caldas, Colombia	CM	MAN1C	5.07	-75.52	10	2199	86	134	283.018178	203.826588	70.532268
Salento, Quindio, Colombia	CM	SLNT	4.64	-75.57	10	1990	89	137	156.898439	142.872074	81.001457
Calarca, Quindio, Colombia	CM	CCALA	4.51	-75.63	10	1795	91	138	70.103647	87.29783	43.428818